



# MME Standard Operating Procedure (SOP)


<b>Name</b>	<ul style="list-style-type: none"> <li>Huys ESD Machine #2</li> </ul>
<b>Description</b>	<ul style="list-style-type: none"> <li>R&amp;D Variable Parameters ESD Machine</li> </ul>
<b>Location</b>	<ul style="list-style-type: none"> <li>E3-2107 "Welding Lab"</li> </ul>
<b>SOP Creation Date</b>	<ul style="list-style-type: none"> <li>2015-3-31</li> </ul>
<b>SOP Created By</b>	<ul style="list-style-type: none"> <li>Foss Jiao, Dominic Leung</li> </ul>
<b>SOP Revision Date</b>	<ul style="list-style-type: none"> <li></li> </ul>
<b>SOP Revised By</b>	<ul style="list-style-type: none"> <li></li> </ul>
<b>SOP Location</b>	<ul style="list-style-type: none"> <li><a href="http://inv.mme.uwaterloo.ca">inv.mme.uwaterloo.ca</a></li> </ul>
<b>Manual Location</b>	<ul style="list-style-type: none"> <li>E3-2107 "Welding Lab"</li> </ul>
<b>Equipment Owner</b>	<ul style="list-style-type: none"> <li>Professor Norman Zhou (x36095) &amp; Huys Industries</li> </ul>
<b>Authorized Trainers</b>	<ul style="list-style-type: none"> <li>Joyce Koo, Foss Jiao, Stephen Peterkin and Dominic Leung</li> </ul>
<b>Support Technicians</b>	<ul style="list-style-type: none"> <li>Dominic Leung</li> </ul>



<b>Significant Hazards</b>	<ul style="list-style-type: none"> <li>Light <ul style="list-style-type: none"> <li>Weak UV radiation from the electrode sparks</li> <li>Weak UV radiation from red hot metals</li> </ul> </li> <li>Burns <ul style="list-style-type: none"> <li>Operating electrode tips reach red hot temperatures</li> </ul> </li> <li>Fumes <ul style="list-style-type: none"> <li>Some metals may be rapidly oxidized or vaporized during deposition forming toxic vapors</li> </ul> </li> <li>Vibrations <ul style="list-style-type: none"> <li>Vibrations from the applicator would cause bodily fatigue after an extended period of operation</li> </ul> </li> <li>Noise <ul style="list-style-type: none"> <li>Extended use of depending on the applicator can cause hearing damage</li> </ul> </li> </ul>
<b>Administrative Controls</b>	<ul style="list-style-type: none"> <li>Scheduling of ESD depositions shall be scheduled amongst the authorized personnel</li> <li>Only authorized personnel shall operate, maintain or service the ESD Machine</li> <li>Reduce extended depositions to prevent fatigue, eye damage and hearing damage</li> <li>Always run the lab ventilation fan when depositing</li> </ul>
<b>Engineering Controls</b>	<ul style="list-style-type: none"> <li>Equipment design prevents excess large short circuit discharges while the applicator is not rotating / vibrating</li> <li>Equipment discharge and resistance requirements prevents electrocution during operation</li> </ul>

<b>PPE Required</b>	<p>Typical operating procedures and papers on ESD stress that there are little to no required PPE requirements</p> <ul style="list-style-type: none"> <li>• Eye protection is required during ESD <ul style="list-style-type: none"> <li>○ Clear safety glasses are the minimum to spectate the ESD equipment</li> <li>○ Operators should use tinted safety glasses or brazing goggles during extended ESD use, as the bright sparks and weak UV radiation may strain eyes</li> <li>○ Shades beyond 5 may impair vision during deposition and are not recommended</li> </ul> </li> <li>• Gloves are to be worn to protect from sparks during deposition as well as prevent burns from handling hot substrates and electrodes post deposition</li> <li>• Long sleeves or lab coats are required to protect wrists and arms from sparks and burns resulting from deposition and contact with hot substrates / electrodes</li> <li>• Hearing protection can be used if loud applicators are being utilized for extended periods of time</li> </ul>
<b>Relevant Standards and Codes</b>	<ul style="list-style-type: none"> <li>• none</li> </ul>
<b>Relevant MSDS</b>	<p>All MSDSs can be found at <a href="http://msds.mme.uwaterloo.ca">msds.mme.uwaterloo.ca</a></p> <ul style="list-style-type: none"> <li>• Argon Compressed gas</li> <li>• LECO diamond spray</li> </ul>
<b>Accident Procedure</b>	<ul style="list-style-type: none"> <li>• All accidents are to be reposted to the supervisor as soon as possible <ul style="list-style-type: none"> <li>○ Treat minor incidents with First Aid kits or contact UW Health services 599-888-4096 x84096</li> <li>○ Contact Dr. Joyce Koo or Professor Norman Zhou</li> <li>○ Complete incident report</li> </ul> </li> <li>• In the event of serious injury / illness Call 911 <ul style="list-style-type: none"> <li>○ Also contact campus police services 519-888-4911 or x22222</li> <li>○ Complete incident report</li> </ul> </li> </ul>
<b>Emergency Shutdown Procedure</b>	<ul style="list-style-type: none"> <li>• Injury <ul style="list-style-type: none"> <li>○ Turn off the Huys ESD Machine using the power ON / OFF switch</li> <li>○ Follow accident procedure</li> <li>○ Complete incident report</li> </ul> </li> <li>• Fire <ul style="list-style-type: none"> <li>○ Turn off the Huys ESD machine if safe to do so <ul style="list-style-type: none"> <li>▪ Disconnect the power to the machine if safe to do so and necessary</li> <li>▪ Turn off the exhaust fan to the lab if safe to do so</li> <li>▪ Exit the area and assemble outside as stated in the Building Emergency Plan</li> <li>▪ Access fire extinguisher if the fire is small enough</li> <li>▪ Fire extinguisher located on the wall in the corridor outside the lab</li> <li>▪ Activate wall mounted fire alarms</li> <li>▪ Report any information about the fire to the UW Police and Fire Department</li> </ul> </li> </ul> </li> </ul>





### Pre-start Checklist

- Ensure that the lab ventilation fan is on
- Ensure that the door to the lab is closed to protect passers by
- Ensure that the deposition area is clear of flammable media and clutter
- Check the operating condition of the equipment
  - Check the machine power, applicator and grounding cables for fraying and damage
- Do appropriate PPE as listed in the operating procedure
  - Ensure that the operator will not contact the fixtures, ground, substrate or electrode while operating with bare skin
- Ensure that a power bar is securely connected to the wall outlet 15A 120V 60hz
- Ensure that the power switch of the applicator speed control is set to OFF
- Ensure the power switch of the power bar is set to OFF before the ESD machine, the spindle speed control & applicator speed control units are connected to the power bar
- Ensure the spindle unit securely sits on a bench, and is free and safe to rotate
- Ensure that the applicator speed control unit is securely mounted to a wall
- Ensure that a ground cable is securely connecting the -ve terminal of the ESD machine and the terminal of the spindle unit
- Ensure that the ESD power cable from the applicator is securely connected to the +ve terminal of the ESD machine
- Ensure that the cooling fan is operating when the power is ON

### Start-up Procedure

- Attach the applicator and ground clamp before turning on the machine
- Ensure that the power bar is securely connected to the wall outlet 15A 120V 60hz
- Ensure that the ESD machine, spindle speed control unit and the applicator speed control unit power cables are securely connected to the power bar
- Attach an electrode cap, to be ESD coated, to the spindle unit
- Secure an ESD electrode into the applicator (may require the use of a hex key to the holder)

### Operating Procedure

- Turn on the power bar (Ensure that the applicator speed control switch is set to OFF)
- Turn on the ESD machine. Ensure the LCD display shows a normal power up sequence
- Ensure the following ESD parameter values for normal coating conditions with the use of the keypad and LCD display units on the front panel: (Find detailed information in user manuals)
  - ARC Voltage = 5 - 45, default = 20
  - ESD Voltage = 25 - 45, default = 35
  - ESD Voltag2 = 10 - 45, default = 20
  - ARC Charge = 10 - 35, default = 25
  - ESD Charge = 10 - 45, default = 40
  - Discharge DLY = 0 - 5, default = 1
  - Recharge DLY = 0 - 5, default = 2
  - Hi Pulse = 1 - 5, default = 2
  - Lo Pulse = 0 - 5, default = 2
  - Cntrl Mode = 0 - 5, default = 1
- Ensure that the electrode cap on the spindle is rotating in a symmetrical manner. Redo the sitting if necessary
- Set the spindle speed control to desired value and ensure that the spindle is spinning freely
- Set the power switch of the applicator speed control device to the desired rotational direction, FWD or REV. The applicator should start vibration immediately.
- Begin deposition
- Adjust ESD coating parameters when needed through the keypad and LCD display units on the front panel

### Shutdown Procedure

- Turn off the ESD machine
- Turn off the FWD/OFF/REV switch of the applicator speed control unit
- Carefully place the applicator where the electrode will not damage any of the equipment or fixtures (as it remains hot after deposition)
- Turn off the ON/OFF switch of the power bar

### Maintenance and Repair

- Clear the dust collected on the filter screens on the side of the chassis
- Contact Dominic Leung or other trained staffs for serious problem and electrical issues