Equipment	Emergency Procedure	
Angstrom EvoVac	Abort process; EMO	
AJA Sputterer	Abort process; EMO	
Edwards Sputterer	RF off, gas flow off	
Intlvac - E-Beam	STOP controller	
Intlvac - Thermal	STOP controller	
Se evaporator	Abort process, boat power off	
WLOS	safe to leave	
WLO1 cluster	EMO to stop gas flow	
WLO2 cluster	EMO to stop gas flow	
Wet benches	Turn off hotplates; Turn off ultrasonic OR EPO	
RIE systems	EMO	
MA6	safe to leave	
MJB3	safe to leave	
Dicing saw	EMO	