



MATERIAL SAFETY DATA SHEET

1. CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

MATHESON TRI-GAS, INC.

959 ROUTE 46 EAST

PARSIPPANY, NEW JERSEY 07054-0624

EMERGENCY CONTACT:

CHEMTREC 1-800-424-9300

INFORMATION CONTACT:

973-257-1100

SUBSTANCE: DIBORANE

TRADE NAMES/SYNONYMS:

MTG MSDS 111; BOROETHANE; BOROHYDRIDE; BIBORON HEXAHYDRIDE; DIBORANE(6); UN 1911; B2H6; MAT06650; RTECS HQ9275000

CHEMICAL FAMILY: metal

CREATION DATE: Jan 24 1989 **REVISION DATE:** Dec 15 2003

2. COMPOSITION, INFORMATION ON INGREDIENTS

COMPONENT: DIBORANE CAS NUMBER: 19287-45-7 PERCENTAGE: 100.0

3. HAZARDS IDENTIFICATION

NFPA RATINGS (SCALE 0-4): HEALTH=4 FIRE=4 REACTIVITY=3

EMERGENCY OVERVIEW:

COLOR: colorless
PHYSICAL FORM: gas

ODOR: irritating odor

MAJOR HEALTH HAZARDS: potentially fatal if inhaled, respiratory tract burns, skin irritation, eye

irritation

PHYSICAL HAZARDS: May explode when heated. Flammable gas. May cause flash fire.

POTENTIAL HEALTH EFFECTS:

INHALATION:

SHORT TERM EXPOSURE: burns, difficulty breathing, headache, dizziness, blurred vision, lung







congestion, kidney damage, liver damage, death

LONG TERM EXPOSURE: same as effects reported in short term exposure

SKIN CONTACT:

SHORT TERM EXPOSURE: irritation (possibly severe) **LONG TERM EXPOSURE:** no information is available

EYE CONTACT:

SHORT TERM EXPOSURE: irritation (possibly severe) **LONG TERM EXPOSURE:** no information is available

INGESTION:

SHORT TERM EXPOSURE: no information on significant adverse effects

LONG TERM EXPOSURE: no information is available

4. FIRST AID MEASURES

INHALATION: If adverse effects occur, remove to uncontaminated area. Give artificial respiration if not breathing. If breathing is difficult, oxygen should be administered by qualified personnel. Get immediate medical attention.

SKIN CONTACT: Wash skin with soap and water for at least 15 minutes while removing contaminated clothing and shoes. Get medical attention, if needed. Thoroughly clean and dry contaminated clothing and shoes before reuse.

EYE CONTACT: Flush eyes with plenty of water for at least 15 minutes. Then get immediate medical attention.

INGESTION: If a large amount is swallowed, get medical attention.

NOTE TO PHYSICIAN: For inhalation, consider oxygen.

5. FIRE FIGHTING MEASURES

FIRE AND EXPLOSION HAZARDS: Severe fire hazard. Gas/air mixtures are explosive.

EXTINGUISHING MEDIA: Let burn unless leak can be stopped immediately.

FIRE FIGHTING: Move container from fire area if it can be done without risk. Cool containers with water spray until well after the fire is out. Stay away from the ends of tanks. For fires in cargo or storage area: Cool containers with water from unmanned hose holder or monitor nozzles until well after fire is out. If this is impossible then take the following precautions: Keep unnecessary people away, isolate hazard area and deny entry. Let the fire burn. Withdraw immediately in case of rising sound from venting safety device or any discoloration of tanks due to fire. For tank, rail car or tank truck: Evacuation radius: 800 meters (1/2 mile). Stop flow of gas.

FLASH POINT: -130 F (-90 C) (CC)





LOWER FLAMMABLE LIMIT: 0.8% UPPER FLAMMABLE LIMIT: 88% AUTOIGNITION: 100-126 F (38-52 C)

6. ACCIDENTAL RELEASE MEASURES

OCCUPATIONAL RELEASE:

Avoid heat, flames, sparks and other sources of ignition. Stop leak if possible without personal risk. Reduce vapors with water spray. Keep unnecessary people away, isolate hazard area and deny entry. Remove sources of ignition. Ventilate closed spaces before entering. Notify Local Emergency Planning Committee and State Emergency Response Commission for release greater than or equal to RQ (U.S. SARA Section 304). If release occurs in the U.S. and is reportable under CERCLA Section 103, notify the National Response Center at (800)424-8802 (USA) or (202)426-2675 (USA).

7. HANDLING AND STORAGE

STORAGE: Store and handle in accordance with all current regulations and standards. Protect from physical damage. Store and handle in a detached building. Refrigerate. Store in a well-ventilated area. Avoid contact with air. Keep separated from incompatible substances. Store under an inert atmosphere. Keep separated from incompatible substances. Notify State Emergency Response Commission for storage or use at amounts greater than or equal to the TPQ (U.S. EPA SARA Section 302). SARA Section 303 requires facilities storing a material with a TPQ to participate in local emergency response planning (U.S. EPA 40 CFR 355.30).

8. EXPOSURE CONTROLS, PERSONAL PROTECTION

EXPOSURE LIMITS:

DIBORANE:

0.1 ppm (0.1 mg/m3) OSHA TWA

0.1 ppm ACGIH TWA

0.1 ppm (0.1 mg/m3) NIOSH recommended TWA 10 hour(s)

VENTILATION: Provide local exhaust or process enclosure ventilation system. Ventilation equipment should be explosion-resistant if explosive concentrations of material are present. Ensure compliance with applicable exposure limits.

EYE PROTECTION: Wear splash resistant safety goggles. Provide an emergency eye wash fountain and quick drench shower in the immediate work area.

CLOTHING: Wear appropriate chemical resistant clothing.

GLOVES: Wear appropriate chemical resistant gloves.



The Gas Professionals™ Page 4 of 7

RESPIRATOR: The following respirators and maximum use concentrations are drawn from NIOSH and/or OSHA.

1 ppm

Any supplied-air respirator.

2.5 ppm

Any supplied-air respirator operated in a continuous-flow mode.

5 ppm

Any supplied-air respirator with a tight-fitting facepiece that is operated in a continuous-flow mode.

Any self-contained breathing apparatus with a full facepiece.

Any supplied-air respirator with a full facepiece.

15 ppm

Any supplied-air respirator operated in a pressure-demand or other positive-pressure mode.

Escape -

Any air-purifying respirator with a full facepiece and a canister providing protection against this substance. Any appropriate escape-type, self-contained breathing apparatus.

For Unknown Concentrations or Immediately Dangerous to Life or Health -

Any supplied-air respirator with full facepiece and operated in a pressure-demand or other positive-pressure mode in combination with a separate escape supply.

Any self-contained breathing apparatus with a full facepiece.

9. PHYSICAL AND CHEMICAL PROPERTIES

PHYSICAL STATE: gas

COLOR: colorless **ODOR:** irritating odor

MOLECULAR WEIGHT: 27.68 MOLECULAR FORMULA: B2-H6 BOILING POINT: -134 F (-92 C) FREEZING POINT: -265 F (-165 C)

VAPOR PRESSURE: 27460 mmHg @ 15 C

VAPOR DENSITY (air=1): 0.96

SPECIFIC GRAVITY (water=1): 0.210 @ 15 C

WATER SOLUBILITY: reacts

PH: Not applicable

VOLATILITY: Not applicable **ODOR THRESHOLD:** 2 mg/m3

EVAPORATION RATE: Not applicable

COEFFICIENT OF WATER/OIL DISTRIBUTION: Not applicable

SOLVENT SOLUBILITY:

Soluble: carbon disulfide, ammonium hydroxide, concentrated sulfuric acid

10. STABILITY AND REACTIVITY



Page 5 of 7

REACTIVITY: May decompose explosively when heated above 40 C. May ignite on contact with water or moist air.

CONDITIONS TO AVOID: Avoid heat, flames, sparks and other sources of ignition. Minimize contact with material. Avoid inhalation of material or combustion by-products. Keep out of water supplies and sewers.

INCOMPATIBILITIES: metals, bases, oxidizing materials, combustible materials, halo carbons

HAZARDOUS DECOMPOSITION:

Thermal decomposition products: miscellaneous decomposition products

POLYMERIZATION: Will not polymerize.

11. TOXICOLOGICAL INFORMATION

DIBORANE:

TOXICITY DATA:

40 ppm/4 hour(s) inhalation-rat LC50

LOCAL EFFECTS: Irritant: skin, eye

Corrosive: inhalation

ACUTE TOXICITY LEVEL:

Highly Toxic: inhalation

MUTAGENIC DATA: Available.

12. ECOLOGICAL INFORMATION

Not available

13. DISPOSAL CONSIDERATIONS

Dispose in accordance with all applicable regulations. Subject to disposal regulations: U.S. EPA 40 CFR 262. Hazardous Waste Number(s): D001. D003.

14. TRANSPORT INFORMATION

U.S. DOT 49 CFR 172.101:

PROPER SHIPPING NAME: Diborane

ID NUMBER: UN1911

HAZARD CLASS OR DIVISION: 2.3 **LABELING REQUIREMENTS:** 2.3; 2.1







QUANTITY LIMITATIONS:

PASSENGER AIRCRAFT OR RAILCAR: Forbidden

CARGO AIRCRAFT ONLY: Forbidden

ADDITIONAL SHIPPING DESCRIPTION: Toxic-Inhalation Hazard Zone A

CANADIAN TRANSPORTATION OF DANGEROUS GOODS:

SHIPPING NAME: Diborane, compressed

UN NUMBER: UN1911

CLASS: 2.3; 2.1

15. REGULATORY INFORMATION

U.S. REGULATIONS:

CERCLA SECTIONS 102a/103 HAZARDOUS SUBSTANCES (40 CFR 302.4): Not regulated.

SARA TITLE III SECTION 302 EXTREMELY HAZARDOUS SUBSTANCES (40 CFR 355.30):

DIBORANE: 100 LBS TPQ

SARA TITLE III SECTION 304 EXTREMELY HAZARDOUS SUBSTANCES (40 CFR 355.40):

DIBORANE: 100 LBS RQ

SARA TITLE III SARA SECTIONS 311/312 HAZARDOUS CATEGORIES (40 CFR 370.21):

ACUTE: Yes CHRONIC: No FIRE: Yes

REACTIVE: Yes

SUDDEN RELEASE: Yes

SARA TITLE III SECTION 313 (40 CFR 372.65): Not regulated.

OSHA PROCESS SAFETY (29CFR1910.119):

DIBORANE: 100 LBS TQ

STATE REGULATIONS:

California Proposition 65: Not regulated.

CANADIAN REGULATIONS:

WHMIS CLASSIFICATION: ABD1

NATIONAL INVENTORY STATUS:

U.S. INVENTORY (TSCA): Listed on inventory.

TSCA 12(b) EXPORT NOTIFICATION: Not listed.

CANADA INVENTORY (DSL/NDSL): Not determined.



16. OTHER INFORMATION

©Copyright 1984-2006 MDL Information Systems, Inc. All rights reserved.

MATHESON TRI-GAS, INC. MAKES NO EXPRESS OR IMPLIED WARRANTIES, GUARANTEES OR REPRESENTATIONS REGARDING THE PRODUCT OR THE INFORMATION HEREIN, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR USE. MATHESON TRI-GAS, INC. SHALL NOT BE LIABLE FOR ANY PERSONAL INJURY, PROPERTY OR OTHER DAMAGES OF ANY NATURE, WHETHER COMPENSATORY, CONSEQUENTIAL, EXEMPLARY, OR OTHERWISE, RESULTING FROM ANY PUBLICATION, USE OR RELIANCE UPON THE INFORMATION HEREIN.